

SOIL REPORT

OCOTILLO RD

OCOTILLO RD

BO

CABANARD

HT

CABRITO RD SE

Soil

Non-Irrigated



Boundary: 1 ac

Code

Description

CPI

NCCPI

CAP



Wildlife / Forestry

Limited Grazing

Moderate Grazing

Intense Grazing

Limited Farming

Moderate Farming

Intense Farming

Very Intense Farming

HT

Hondale-Mimbres complex

-

12

7s



Totals

1 ac



0 CPI

Average

12 NCCPI

Average

7 Cap.

Average